2

SECRET
Approved For Release 2003/05/14 : CIA-RDP78B05171A000800050076-4

MPIC/TSSG/RED-1817-69 22 September 1969

| UBJECT : GSA Inspection o   |   |
|---|---|
| EFERENCE: NPIC/TSSG/DED-17  | 40-69, 23 July 1969   |
| 1. On 17 September 196 installed in   | 9, the Silver Recovery System,  was inspected by electrical foreman, GSA, Anacostia hat the installation met the GSA Electrical |
| ode and that the plumbing f   | ixtures, piping, valves, etc. were in accord The inspection was set-up with the cooperation                                     |
| and the GSA repr  | system were reviewed by esentatives. There were no discrepancies electrical system inspection revealed the                      |
| -   | grounding wires incorrect - now corrected.  to be replaced with waterproof connectors -   |
| 0 433444 33 43 3  | ischarge of the caustic solution into the   |
| uilding sewer system was di   | be no contamination or other effects arising  |
| uilding sewer system was di<br>etermined that there would<br>rom the effluent discharge | be no contamination or other effects arising of the system.  felt that this inspection fulfills items 2d,                       |

**Declass Review by** NIMA/DOD